


Ferric cores symbols

1/1

Symbols	Description	Symbols	Description
	Ferric core		Indicator of the direction of flow up and running from left to right
	Direction indicator and flow down stream from left to right		Iron core with winding
	Ferric Ceontral with winding N = turns of the winding		Two conductors through an iron core and a winding on one core
	Ferric core with three windings		Ferrite on a wire
	Ferrite on a wire		

More information about these and other symbols www.electronic-symbols.com