










Ferrite Cores Symbols [[Go to Website](#)]

 <p>Ferrite core Magnetic core</p>	 <p>Magnetic flux Indicator of the upwards direction of flow and the direction from left to right of the current</p>	 <p>Magnetic flux Indicator of the downwards direction of flow and the direction from left to right of the current</p>	 <p>Iron core with winding</p>
 <p>Ferrite core with winding N = turns of the winding</p>	 <p>Two conductors through an iron core and a winding on one core</p>	 <p>Ferrite on a wire Ferrite bead Ferrite choke</p>	 <p>Ferrite ring on a wire Ferrite bead Ferrite choke</p>
 <p>Ferrite core with three windings</p>			