






































# Windings Connection Symbols [\[ Go to Website \]](#)

 <p>Winding</p>	 <p>2 Separated winding</p>	 <p>3 Separated winding</p>	 <p>6 Separated winding</p>
 <p>6 interconnected windings</p>	 <p>Interconnected multiple-phase winding</p>	 <p>2-phase winding</p>	 <p>3-phase Scott</p>
 <p>2-phase winding 4-wire separated connection</p>	 <p>2-phase winding 4-wire connection</p>	 <p>2-phase, 3-wire connection with ground</p>	 <p>3-phase, 4-wire ungrounded</p>
 <p>2-phase, 5-wire grounded</p>	 <p>3-phase wye with neutral grounded</p>	 <p>3-phase winding 4-wire connection</p>	 <p>3-phase winding 4-wire connection, neutral brought out</p>
 <p>3-phase winding, 4-wire grounded connection</p>	 <p>4-phase winding</p>	 <p>3-phase wye or star</p>	 <p>4-phase winding neutral brought out</p>

All Electrical & Electronic Symbols in <https://www.electrical-symbols.com>

# Windings Connection Symbols [\[ Go to Website \]](#)

 <p>4-phase grounded winding</p>	 <p>3-phase grounded zig-zag</p>	 <p>3-phase ungrounded zig-zag</p>	 <p>6-phase double zig-zag with grounded neutral</p>
 <p>3-phase, 3-wire delta</p>	 <p>3-phase, 4-wire grounded delta connection</p>	 <p>3-phase, 3-wire delta with ground</p>	 <p>3-phase winding, open delta connection</p>
 <p>3-phase winding, 4-wire delta connection</p>	 <p>3-phase winding, open delta grounded connection</p>	 <p>3-phase winding open delta connection</p>	 <p>3-phase winding, open delta grounded connection</p>
 <p>6-phase winding double star connection</p>	 <p>6-phase winding, double star grounded connection</p>	 <p>6-phase star winding</p>	 <p>6-phase hexagonal winding</p>
 <p>6-phase double delta winding</p>			

All Electrical & Electronic Symbols in <https://www.electrical-symbols.com>