












# Synchronous Motors Symbols [ [Go to Website](#) ]

 <p>Synchronous torque receiver synchronous TR</p>	 <p>Diferential adder transmitter, TDX</p>	 <p>Differential adder transmitter with high power, TDX</p>	 <p>Differential adder receptor with high power, TDR</p>
 <p>Synchro control transmitter terminals</p>	 <p>Synchro solve RS with compensation windings</p>	 <p>Synchro transmitter system with coarse fine control e.g. 60MHz</p>	 <p>DC Synchro control receiver with 8 stages</p>
 <p>Synchro control receiver with waterproof case operated by AF</p>	 <p>Synchro with a wound rotor</p>	 <p>Representation of the coils of a synchro</p>	